

Inspection Photos  
Location Name: Gregory 0780 1-09H  
Location ID: 439603



**Photo 1. Overview of location taken at entrance facing northeast.**



**Photo 2. Overview of location taken at entrance facing southeast.**

Inspection Photos  
Location Name: Gregory 0780 1-09H  
Location ID: 439603



**Photo 3. Oily fluid in bucket without secondary containment. Stained soil.**



**Photo 4. Close-up of contents.**



Inspection Photos  
Location Name: Gregory 0780 1-09H  
Location ID: 439603



**Photo 5. E & P waste stored near perimeter without secondary containment.**



**Photo 6. Close-up of contents.**

Inspection Photos  
Location Name: Gregory 0780 1-09H  
Location ID: 439603



Photo 7. Incomplete tank label.



Photo 8. Incomplete battery sign.

Inspection Photos  
Location Name: Gregory 0780 1-09H  
Location ID: 439603



**Photo 9. Tracking onto highway 14, facing south.**



**Photo 10. Tracking onto highway 14, facing north.**