

Location Name: Ward And Son Operating – Ward #5 Pierce Battery (Rem #8069)
Inspection Date: 3/22/2019



Photo # - 1



Location Name: Ward And Son Operating – Ward #5 Pierce Battery (Rem #8069)
Inspection Date: 3/22/2019



Photo # - 2

Former oil skim pit view west. Excavation filled with snowmelt



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Ward And Son Operating – Ward #5 Pierce Battery (Rem #8069)
Inspection Date: 3/22/2019



Photo # - 3

Former oil skim pit impacted soil stockpile, view southwest



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Ward And Son Operating – Ward #5 Pierce Battery (Rem #8069)
Inspection Date: 3/22/2019



Photo # - 4

Former oil skim pit impacted soil stockpile, view northeast



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources