

**Maralex Resources Inc.**  
**Api # 05-077-08613**  
**Inspection # 675002096**



**Photo of location**

**Maralex Resources Inc.**

**Api # 05-077-08613**

**Inspection # 675002096**



**No Wellhead sign**



**Maralex Resources Inc.**  
**Api # 05-077-08613**  
**Inspection # 675002096**



**Photo of Tank Battery. Berm full of fluid**

Maralex Resources Inc.  
Api # 05-077-08613  
Inspection # 675002096



Faded label on tank



Faded label on tank and fluid in tank containment

**Maralex Resources Inc.**  
**Api # 05-077-08613**  
**Inspection # 675002096**



**Faded label on tank and fluid in tank battery containment**



**Maralex Resources Inc.**  
**Api # 05-077-08613**  
**Inspection # 675002096**



**Sediment running onto location**



**Sediment running onto location**

**Maralex Resources Inc.**  
**Api # 05-077-08613**  
**Inspection # 675002096**



**Heavy sediment from hillside moving onto location**



**Erosion from location moving sediment off location onto access road**



**Maralex Resources Inc.**  
**Api # 05-077-08613**  
**Inspection # 675002096**



**Erosion and sediment running off location**



**Erosion and sediment running off location**