

Maralex Resources Inc.
Api # 05-077-08601
Inspection # 675002097



Photo of location

Maralex Resources Inc.
Api # 05-077-08601
Inspection # 675002097



No Wellhead sign

Maralex Resources Inc.
Api # 05-077-08601
Inspection # 675002097



Photo of Tank Battery. Berm full of fluid

Maralex Resources Inc.
Api # 05-077-08601
Inspection # 675002097



Faded label on tank



Faded label on tank and fluid in tank containment

Maralex Resources Inc.
Api # 05-077-08601
Inspection # 675002097



Sediment running onto location




Sediment running onto location

Maralex Resources Inc.
Api # 05-077-08601
Inspection # 675002097



Heavy sediment from hillside and location moving off location onto access road



Erosion from location moving sediment off location onto access road