

Maralex Resources Inc.

Api # 05-077-08594

Inspection # 675002098



Photo of location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Maralex Resources Inc.

Api # 05-077-08594

Inspection # 675002098



No Wellhead sign debris around pump jack



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Maralex Resources Inc.

Api # 05-077-08594

Inspection # 675002098



Photo of Tank Battery. Berm has debris around it



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Maralex Resources Inc.
Api # 05-077-08594
Inspection # 675002098



Debris around tan and containment



Debris on location

Maralex Resources Inc.
Api # 05-077-08594
Inspection # 675002098



Sediment running onto location



Sediment running off location

Maralex Resources Inc.
Api # 05-077-08594
Inspection # 675002098



Hole from erosion on location causing danger to wildlife, humans and automobiles



Erosion from location moving sediment onto location

Maralex Resources Inc.
Api # 05-077-08594
Inspection # 675002098



Erosion leaving location from BMP not being maintained



Erosion leaving location

Maralex Resources Inc.
Api # 05-077-08594
Inspection # 675002098



Erosion from location going down access road



Erosion from location going down access road

Maralex Resources Inc.
Api # 05-077-08594
Inspection # 675002098



Erosion from location going down the access road



Erosion leaving location on entrance side of location