

Axis Exploration LLC, Bennett A-2
005-07000
Inspection #688304346
3/28/2019
Final PA Inspection




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Tank battery spill excavation

03.28.2019

A wide-angle photograph of a desolate, flat landscape. The ground is a mix of brown and grey, with visible tire tracks curving through the foreground. In the distance, a small, dark structure is visible on the horizon. The sky is filled with heavy, grey clouds.

Well PA, covered and ready
for final reclamation.

03.28.2019



03.28.2019

Well flowline
abandonment.





03.28.2019

Welded pipe joint
and patch.

03.28.

