

Inspection Photos

Operator: Rim Operating
Location/API #: 067-09653
Date: 2-18-2019



Photo 1. View of project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern edge facing eastward. Revegetation is comprised of dense rubber rabbitbrush (*Chrysothamnus nauseosus*).



Photo 3. View of the western project area from the northwestern corner facing southward.