

# Final Reclamation and Stormwater Inspection

March 19, 2019

Operator: NOBLE ENERGY INC # 100322

Location ID: 328562

Inspection Document #: 674902682

Weld County, CO

NESW Section 24 T3N R64W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: NOBLE ENERGY INC /3N64W24  
Location ID: 328562



**Photo 1.** Photo taken from the access road, facing North. Appears Operator has performed final reclamation activities along the access road and location with native perennial grass establishment in some areas.



**Photo 2.** Photo taken from the access road, facing North. See comments from Photo 1.



Inspection Photos  
Location Name: NOBLE ENERGY INC /3N64W24  
Location ID: 328562



**Photo 3.** Photo taken from the access road looking into the location, facing Northwest. See comments from Photo 1.



**Photo 4.** Photo taken from the access road looking into the location, facing Northwest. Appears the Operator has removed all equipment. Also see comments from Photo 1.

Inspection Photos  
Location Name: NOBLE ENERGY INC /3N64W24  
Location ID: 328562



**Photo 5.** Photo taken from the location, facing Northwest. Photo depicts the reclamation is not at percent cover and has non-uniform establishment of perennial cover.



**Photo 6.** Photo taken from the location, facing West. See comments from Photo 5.



Inspection Photos  
Location Name: NOBLE ENERGY INC /3N64W24  
Location ID: 328562



**Photo 5.** Photo taken from the location, facing South.  
See comments from Photo 5.



**Photo 6.** Photo taken from the location, facing Southeast. See comments from Photo 5.