

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401971327

Receive Date:

03/28/2019

Report taken by:

KRIS NEIDEL

Site Investigation and Remediation Workplan (Initial Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC	Operator No: 10598	Phone Numbers Phone: (405) 4295745 Mobile: (405) 6516853
Address: 123 ROBERT S KERR AVE		
City: OKLAHOMA CITY	State: OK Zip: 73102	
Contact Person: Matt Church	Email: mchurch@sandridgeenergy.com	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 12997

Initial Form 27 Document #: 401971327

PURPOSE INFORMATION

- | | |
|--|--|
| <input type="checkbox"/> 901.e. Sensitive Area Determination | <input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water |
| <input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input checked="" type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation | <input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste | <input type="checkbox"/> Rule 906.c.: Director request |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input type="checkbox"/> Other _____ |

SITE INFORMATION

N Multiple Facilities (in accordance with Rule 909.c.)

Facility Type: SPILL OR RELEASE	Facility ID: 462682	API #: _____	County Name: JACKSON
Facility Name: Hebron 18 Pad		Latitude: 40.583974	Longitude: -106.415150
** correct Lat/Long if needed: Latitude: _____ Longitude: _____			
QtrQtr: NWNE	Sec: 18	Twp: 7N	Range: 80W Meridian: 6 Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications GC

Most Sensitive Adjacent Land Use Livestock Grazing

Is domestic water well within 1/4 mile? Yes

Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? Yes

Other Potential Receptors within 1/4 mile

A livestock well, permit number 211370 and receipt number 0434050, is located 0.12 miles south (Static Water Level, SWL 6'10"). A residential well, permit number 200820 and receipt number 0414907, is located 0.21 miles northeast (SWL 5'). A residential/stock well, permit number 292875 and receipt number 3662135, is located 0.23 miles northwest (SWL Not Available). An unnamed irrigation ditch is located 0.11 miles away from the spill location.

SITE INVESTIGATION PLAN

TYPE OF WASTE:

☒ E&P Waste

☐ Other E&P Waste

☐ Non-E&P Waste

☒ Produced Water

☐ Workover Fluids

☐ Oil

☐ Tank Bottoms

☐ Condensate

☐ Pigging Waste

☐ Drilling Fluids

☐ Rig Wash

☐ Drill Cuttings

☐ Spent Filters

☐ Pit Bottoms

☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	SOILS	30 cubic yards	Form 19 Spill Investigation

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Initial Form 19 was submitted 2/26/2019. A hydrovac and excavation equipment were dispatched immediately and impacted materials were removed to the extent that frozen ground conditions would allow on 2/27/2019. A Supplemental Form 19 was submitted 3/8/2019 requesting the Spill/Release remain open until analytical results were recieved.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

On 3/1/2019, 1 soil grab sample was collected within the spill area (40.583969, -106.415234 / PID=3.8 PPM / 1-2 inches below ground surface) and sent to the laboratory for analysis. Confirmation soil samples will be collected, after excavation is completed, and sent to a laboratory for analysis.

Proposed Groundwater Sampling

☐ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 1

Number of soil samples exceeding 910-1 1

Was the areal and vertical extent of soil contamination delineated? Yes

Approximate areal extent (square feet) 150

NA / ND

-- Highest concentration of TPH (mg/kg) 310.1
 2

-- Highest concentration of SAR 25.3

BTEX > 910-1 No

Vertical Extent > 910-1 (in feet) 0

Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet)

Number of groundwater monitoring wells installed

Number of groundwater samples exceeding 910-1

 Highest concentration of Benzene (µg/l)

 Highest concentration of Toluene (µg/l)

 Highest concentration of Ethylbenzene (µg/l)

 Highest concentration of Xylene (µg/l)

 Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected

 Number of surface water samples exceeding 910-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☐ Is further site investigation required?

REMEDIAL ACTION PLAN

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

SandRidge has and will continue to conduct source removal of the impacted soil via dig and haul activities.

REMEDICATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Hydrovac and excavation equipment have removed the majority of impacted materials. A estimated total of 25 BBLs of fluid were recovered, 10 BBLs of flowback water and another 15 BBLs of snow melt and hot water used during the hydro vac cleanup process. The soil sample collected on 3/1/2019 contained elevated EC and SAR, above Table 910-1 allowable concentrations. Therefore SandRidge is requesting project transfer to a Form 27 Remediation Workplan. Further excavation within the spill area will be completed as soon as feasible, depending upon when winter conditions subside. Impacted materials will be disposed at a properly licensed disposal facility. Clean backfill material will be spread on the location when confirmation soil samples indicate that all impacted materials have been removed.

Soil Remediation Summary

☐ In Situ

_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Air sparge / Soil vapor extraction
_____ Natural Attenuation
_____ Other _____

☒ Ex Situ

Yes _____ Excavate and offsite disposal
If Yes: Estimated Volume (Cubic Yards) _____ 5
Name of Licensed Disposal Facility or COGCC Facility ID # _____ 211979
_____ Excavate and onsite remediation
_____ Land Treatment
_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Other _____

Groundwater Remediation Summary

☐ _____ Bioremediation (or enhanced bioremediation)
☐ _____ Chemical oxidation
☐ _____ Air sparge / Soil vapor extraction
☐ _____ Natural Attenuation
☐ _____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

REMEDATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: ☐ Quarterly ☐ Semi-Annually ☐ Annually ☐ Other _____

Report Type: ☐ Groundwater Monitoring ☐ Land Treatment Progress Report ☐ O&M Report
☐ Other _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? _____

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The facility is presently in use and reclamation activities are not warranted at this time onsite.

Is the described reclamation complete? _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim? ☐ Final?

Did the Surface Owner approve the seed mix? _____

If NO, does the seed mix comply with local soil conservation district recommendations? _____

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 02/26/2019

Actual Spill or Release date, if known. 02/25/2019

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 02/26/2019

Date of commencement of Site Investigation. 02/26/2019

Date of completion of Site Investigation. _____

REMEDIAL ACTION DATES

Date of commencement of Remediation. 02/26/2019

Date of completion of Remediation. _____

SITE RECLAMATION DATES

Date of commencement of Reclamation. _____

Date of completion of Reclamation. _____

OPERATOR COMMENT

Further excavation of the impacted area will be completed as soon as feasible, depending upon when winter conditions subside. Upon confirmation that impacted soils have been excavated from the spill area, a Form 27 Supplemental Report will be submitted that will include all waste disposal manifests for this remediation project.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Joel Mason

Title: Project Manager

Submit Date: 03/28/2019

Email: joel.mason@absarokasolutions.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: KRIS NEIDEL

Date: 04/01/2019

Remediation Project Number: 12997

COA Type**Description**

	A request to close spill number 462682 should be submitted on a supplemental Form 19, the Remediation number that is generated from this report will be required on the Form 19.
	Site assessment should be done as soon as practical. This document states that additional soil will be removed, confirmation samples should be taken in the excavation to confirm removal of impacted soil.
	The impacted area should be observed daily, impacted material should be removed as soon as allowable, stormwater should be prevented from contacting impacted soils, confirmation samples should be taken after removal of additional material.

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

401971327	FORM 27-INITIAL-SUBMITTED
401987229	MAP
401987230	SOIL SAMPLE LOCATION MAP
401987231	ANALYTICAL RESULTS
401987232	ANALYTICAL RESULTS
401987235	PHOTOS
401987236	ANALYTICAL RESULTS

Total Attach: 7 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)