

## Inspection Photos

Location Name: Homer Deep Unit 7-23 & HDU 7-23 Spill

Location ID: #436835 Spill ID: #460341

Inspection Date: March 27, 2019



Photo #1 – Tank Battery sign.



Photo #2 – South produced water tank was disconnected on inspection date.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Homer Deep Unit 7-23 & HDU 7-23 Spill

Location ID: #436835 Spill ID: #460341

Inspection Date: March 27, 2019



**Photo #3 – Flowline risers remaining inside of secondary containment for tank battery (northeast side).**



**Photo #4 – Open access panel on east side of south produced water AST.**



## Inspection Photos

Location Name: Homer Deep Unit 7-23 & HDU 7-23 Spill

Location ID: #436835 Spill ID: #460341

Inspection Date: March 27, 2019



**Photo #5 – Unused 1/4" stainless line inside of tank battery secondary containment (south side).**



**Photo #6 – Localized, stained soil outside of tank battery secondary containment (northeast side).**

## Inspection Photos

Location Name: Homer Deep Unit 7-23 & HDU 7-23 Spill

Location ID: #436835 Spill ID: #460341

Inspection Date: March 27, 2019



**Photo #7 – Tank battery under construction on northwest side of pad. Note proximity of tank battery containment to ECD on left side of photo.**



**Photo #8 – Unused equipment stored on northwest side of pad (1).**



## Inspection Photos

Location Name: Homer Deep Unit 7-23 & HDU 7-23 Spill

Location ID: #436835 Spill ID: #460341

Inspection Date: March 27, 2019



**Photo #9 - Unused equipment stored on northwest side of pad (2).**



**Photo #10 – Flowline leading from wellheads to new tank battery.**



## Inspection Photos

Location Name: Homer Deep Unit 7-23 & HDU 7-23 Spill

Location ID: #436835 Spill ID: #460341

Inspection Date: March 27, 2019



**Photo #11 – Lube oil and oil-stained gravel on south side of shed.**



**Photo #12 – View inside of shed from previous photo.**



## Inspection Photos

Location Name: Homer Deep Unit 7-23 & HDU 7-23 Spill

Location ID: #436835 Spill ID: #460341

Inspection Date: March 27, 2019



Photo #13 – Day tanks located on NE side of pad.



Photo #14 – View of stormwater drain on NE side of pad.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources