

# Final Reclamation and Stormwater Inspection

March 19, 2019

Operator: NOBLE ENERGY INC # 100322

Location ID: 329205

Inspection Document #: 674902684

Weld County, CO

SESW Section 23 T3N R64W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: NOBLE ENERGY INC /3N64W23  
Location ID: 319479



**Photo 1.** Photo taken from the access road facing East. It does not appear reclamation work has been performed on the access road



**Photo 2.** Photo taken from the access road facing West. See comments from Photo 1.

## Inspection Photos

Location Name: NOBLE ENERGY INC /3N64W23

Location ID: 319479



**Photo 3.** Photo taken looking into the location, facing East. Appears Operator has removed all equipment and a new location is being constructed .



**Photo 4.** Photo taken from the access road, facing West. See comments from Photo 1.