

Inspection Photos

Location Name: SCHANK J-65N66W /35SENW

Location #: 336706



Photo #1

Schank J 35-06 (05-123-19202) Wellsite
No Emergency contact number posted
from prior FIR



Photo #2

Schank J 35-06 Wellsite
Shut-In | SI
Emergency contact number NOW posted



Inspection Photos
Location Name: SCHANK J-65N66W /35SENW
Location #: 336706



Photo #3
Schank J 35-20 (05-123-26252) Wellsite
No Emergency contact number posted
Trash – pipe sealant can
from prior FIR



Photo #4
Schank J 35-20 Wellsite
Emergency contact number NOW posted
Trash – Removed

Inspection Photos

Location Name: SCHANK J-65N66W /35SENW

Location #: 336706



Photo #5

Schank J 35-21 (05-123-26443) Wellsite

No Emergency contact number posted

from prior FIR



Photo #6

Schank J 35-21 Wellsite

Emergency contact number NOW posted



Inspection Photos

Location Name: SCHANK J-65N66W /35SENW

Location #: 336706



Photo #7

Schank # 2, J 35-06, 35-20, 35-21

Battery site

from prior FIR



Photo #8

Schank # 2, J 35-06, 35-20, 35-21

Battery site



Inspection Photos

Location Name: SCHANK J-65N66W /35SENW

Location #: 336706



Photo #9

Schank # 2, J 35-06, 35-20, 35-21 Battery site

Unused Automation controls

from prior FIR



Photo #10

Schank # 2, J 35-06, 35-20, 35-21 Battery site

Unused Automation controls - Removed



Inspection Photos

Location Name: SCHANK J-65N66W /35SEW

Location #: 336706



Photo #11

Schank # 2, J 35-06, 35-20, 35-21 Battery site

Wood debris near ECD line

from prior FIR



Photo #12

Schank # 2, J 35-06, 35-20, 35-21 Battery site

Wood debris near ECD line - Removed

