

Inspection Photos
Location Name: Schuyler 34-9 #30-2
API: 05-067-08111



Schuyler 34-9 #30-2 well head is stained and wet. Stained gravel surrounding well head.



Pooled fluids and discolored soil surrounding #30-2 well head.

Inspection Photos
Location Name: Schuyler 34-9 #30-2
API: 05-067-08111



**Fluid flow path towards the western edge of location.
Discolored soil in vicinity of fluid.**

Mounds at animal burrows appear to be drill cuttings.