

Inspection Photos
Location Name: Wiedeman J /27-28D
Location #: 332095



Photo #1
Gold J 22-25 (05-123-21829) Wellsite
Weeds
Unused Methanol drum & stand
from prior FIR



Photo #2
Gold J 22-25 Wellsite
Shut-In | SI
Weeds - Mitigated
Unused Methanol drum & stand - Removed

Inspection Photos

Location Name: Wiedeman J /27-28D

Location #: 332095



Colorado Oil & Gas Conservation Commission
40.37985, -104.76809, 1443.0m, 292°
2019/04/02 03:38:56 PM

Photo #3

Gold #1, J 22-25, A J Gold 22-11 Battery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources