

GV 80-4
Api# 05-045-06687
Inspection # 689702972



GV 80-4
Api# 05-045-06687
Inspection # 689702972



Dead weed rubbish on location.

GV 80-4
Api# 05-045-06687
Inspection # 689702972



Dead weed rubbish on location.

GV 80-4
Api# 05-045-06687
Inspection # 689702972



Dead weed rubbish on location.

GV 80-4
Api# 05-045-06687
Inspection # 689702972



Dead weed rubbish on location.

GV 80-4
Api# 05-045-06687
Inspection # 689702972



Dead weed rubbish on location.

GV 80-4
Api# 05-045-06687
Inspection # 689702972



Dead weed rubbish on location.

GV 80-4
Api# 05-045-06687
Inspection # 689702972



Unmarked deadmen.

GV 80-4
Api# 05-045-06687
Inspection # 689702972



Secondary containments full.

GV 80-4
Api# 05-045-06687
Inspection # 689702972



Sediment build up in checkdam.

GV 80-4
Api# 05-045-06687
Inspection # 689702972



Fencing down around tank battery.