Inspector Name: LONGWORTH, MIKE

FORM INSP

Rev X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/02/2019
Submitted Date:

04/02/2019
Document Number:

FIELD INSPECTION FORM

					. •				6	89702974
Loc ID	Inspector Name	e:	On-Site I	Insped	spection Status Summary:			ıs Summary:		
334654	LONGWORTH, MIKE 2A			•	Doc Num: X TH			THIS IS A FOLLOW UP INSPECTION		
Operator Information:							OLLOW UP INSPECTI	ON REQI	JIRED	
OGCC Operator Number: 96850								ECTION R	EQUIRED	
Name of Operator: TEP ROCKY MOUNTAIN LLC 20 Number of Commer									nte	
Address: PO BOX 370								Number of Corrective		
City: F	PARACHUTE	State:	СО	Z	Zip: 81635	;		orrective Action Response		
, <u> </u>					·			· · · · · · · · · · · · · · · · · · ·		
							P	NY CORRECTIVE AC REVIOUS INSPECTION EEN ADDRESSED AF	NS THAT	HAVE NOT
Contact Inf	ormation:									
Contact Na	ame	Phor	ne	Ema	ail			Comment		
Kellerby, S	haun			sha	un.kellerby@	state.co.	us			
Inspection,	Inspection, Terra TEP 970-285-9377			COGCCInspectionReports@erraep.com						
Inspected F	acilities:									
Facility ID	Туре	Status	Status Date		Well Class	API Num		Facility Name		Insp Status
119	WELL	PR	10/17/2008	GW		045-15440		SAVAGE PA 444-4		PR
121	WELL	PR	01/29/2008	(GW	045-1544	1 1	SAVAGE PA 34-4		PR
122	WELL	PR	08/21/2008	GW		045-1544	12	SAVAGE PA 534-4		PR
123	WELL	PR	08/03/2008	(GW	045-15443		SAVAGE PA 543-4		PR
414355	WELL	PR	05/10/2011	(GW	V 045-18831		Savage PA 44-4		PR
414356	WELL	PR	04/11/2011	(GW 045-18832		32	Savage PA 344-4		PR
414357	WELL	PR	08/16/2011	(GW	045-18833		Savage PA 334-4		PR
414364	WELL	PR	09/06/2011	(GW	045-18834		Savage PA 343-4		PR
414365	WELL	PR	07/31/2011	(GW	045-18835		Savage PA 33-4		PR
414368	WELL	PR	08/02/2011	(GW	045-18836		Savage PA 434-4		PR
414373	WELL	PR	08/31/2011	GW		045-18837		Savage PA 333-4		PR
414383	WELL	PR	11/01/2011	(GW	045-18838		Savage PA 443-4		PR
414384	WELL	PR	05/10/2011	GW		045-18839		Savage PA 544-4		PR
418495	WELL	PR	10/25/2011	(GW	045-1971	7	Savage PA 431-9		PR
418499	WELL	PR	05/01/2011	(GW	045-1972	20	Savage PA 541-9		PR
418501	WELL	PR	07/13/2011		GW	045-1972	22	Savage PA 331-9		PR
General Co	mment:	_							_	
Follow up t	to inspection 68970	2437								

Inspector Name: LONGWORTH, MIKE

<u>Location</u>								
Lease Road:								
Туре	Access	ccess						
comment:	Road is rutted.							
Corrective ActionL				Date:				
Overall Good:								
Signs/Marker:								
Туре	WELLHEAD							
Comment:								
Corrective Action:				Date	:			
Туре	TANK LABELS/PLACARI	DS .						
Comment:								
Corrective Action:				Date	:			
Type	BATTERY							
Comment:								
Corrective Action:				Date	:			
Emergency Contact I	Number:							
Comment:	970-285-9377							
Corrective Action:				Date:				
Good Housekeeping								
Туре	DEBRIS							
	Corective action not made							
	Dead weed rubbish on loc							
Corrective Action:	Comply with Rule 603.f .			Date	01/28/2019			
Overall Good:								
Spills:								
Туре	Area	Volume						
In Containment: No								
Comment: Comment Comme								
Multiple Spills and Releases?								
Venting:								
Yes/No	NO							
Comment:								
Corrective Action:	Date:							
Flaring:								
Туре								
Comment:								
Corrective Action:	Date:							

inspector ivai	IIIe. LONGV	VORTH, MIKI			I Facilities				
				Inspected	d Facilities				
Facility ID:	119	Type:	WELL	API Number:	045-15440	Status: _	PR	Insp. Status:	PR
				Produc	ing Well				
Co	mment: Pro	ducing well							
Corrective	Action:							Date:	
Facility ID:	121	Type:	WELL	API Number:	045-15441	Status:	PR	Insp. Status:	PR
				Produc	ing Well				
Co	mment: Pro	oducing well							
Corrective	Action:							Date:	
Facility ID:	122	Type:	WELL	API Number:	045-15442	Status:	PR	Insp. Status:	PR
				Produc	ing Well				
Co	omment: Pro	oducing well							
Corrective	Action:							Date:	
Facility ID:	123	Type:	WELL	API Number:	045-15443	Status:	PR	Insp. Status:	PR
		<u> </u>		Produc	ing Well				
Co	mment: Pro	oducing well							
Corrective								Date:	
Facility ID:	414355	Type:	WELL	API Number:	045-18831	Status:	PR	Insp. Status:	PR
				-	ing Well	<u> </u>		<u> </u>	
Co	mment. Pro	oducing well							
Corrective								Date:	
	7 (000)							Date.	
Facility ID:	414356	Type:	WELL	API Number:	045-18832	Status:	PR	Insp. Status:	PR
	+14000	<u> </u>	VVLLL	-	ing Well		110		
Co	mmont: Dr	oducing well		rioduc	<u>iiig weii</u>				
Corrective		ducing wen						Dete	
Corrective	Action.							Date:	
Facility ID:	414357	Type:	WELL	API Number:	045-18833	Status:	PR	Insp. Status:	PR
T acinty ID	414007		VVLLL	-		Siaius	I'IX	ilisp. Status.	I IX
		1		Produc	ing Well				
		oducing well							
Corrective	Action:							Date:	
— ••• •=		_	14		0.45	<u> </u>			D -
Facility ID:	414364	Type:	WELL	API Number:	045-18834	Status: _	PR	Insp. Status:	PR
				Produc	ing Well				
		oducing well							
Corrective	Action:							Date:	

——————————————————————————————————————	ine. LONGW	ORIH, MIKE	-						
Facility ID:	414365	Type:	WELL	API Number:	045-18835	Status:	PR	Insp. Status:	PR
				Produc	ing Well				
Co	omment: Pro	ducing well							
Corrective	e Action:							Date:	
Facility ID:	414368		WELL	API Number:	045-18836	Status: _	PR	Insp. Status:	PR
_	_			Produc	ing Well				
	omment: Pro	ducing well							
Corrective	e Action:							Date:	
E386 (D)	44.4070	T:	\A/E11	A DI Niversia a m	045 40007	Otation	DD	In an Otation	DD
Facility ID:	414373	Type:	WELL	API Number:	045-18837	Status: _	PR	Insp. Status: _	PR
_		almain a		Produc	ing Well				
	omment: Pro	oducing well						Data	
Corrective	e Action:							Date:	
Facility ID:	414383	Typo:	WELL	API Number:	045-18838	Status:	PR	Insp. Status:	PR
	414303		VVELL	-		Status	PK	insp. Status	PK
C	omment: Pro	oducina wall		Produc	ing Well				
Corrective		ducing well						Date:	
Corrective	e Action.							Date.	
Facility ID:	414384	Type:	WELL	API Number:	045-18839	Status:	PR	Insp. Status:	PR
<u> </u>		<u> </u>		Produc	ing Well			<u> </u>	
Co	omment: Pro	ducing well		<u></u>					
Corrective	e Action:							Date:	
Facility ID:	418495	Type:	WELL	API Number:	045-19717	Status:	PR	Insp. Status:	PR
				Produc	ing Well				
Co	omment: Pro	ducing well							
Corrective	e Action:							Date:	
Facility ID: _	418499	Type:	WELL	API Number:	045-19720	Status: _	PR	Insp. Status:	PR
				Produc	ing Well				
Co	omment: Pro	ducing well							
Corrective	e Action:							Date:	
	•								
Facility ID: _	418501	Type:	WELL	API Number:	045-19722	Status: _	PR	Insp. Status:	PR
				Produc	ing Well				
Co	omment: Pro	ducing well							
Corrective	e Action:	<u> </u>						Date:	

Inspector Name: LONGWORTH	I, MIKE		

mspecio	nspector Name: LONGWORTH, MIKE							
				<u>Reclamat</u>	ion - Storm	Water - Pit		
Storm V	Vater:							
Loc Erosion BMPs BMP Maintenance		BMP Maintenance	Lease Road Erosion BMPs		Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compac	tion	Pass						
Gravel		Pass						
					Pass			
			Culverts		Pass			
			Compa	ction	Pass			
	Comment:							
Corrective Action:				Date:				
Pits:	Pits: X NO SURFACE INDICATION OF PIT							
Permit:	Permit: Facility ID Permit I		Num	Expiration Date	Э			
	414553 163102		8					
	414553	163102	8					

Attached Documents

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL
689702975	Inspection 689702974 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4782954

Date Run: 4/3/2019 Doc [#689702974]