

Final Reclamation Inspection

April 1, 2019

Operator: PDC ENERGY INC - 69175

API: 05-123-12560

Inspection Document #: 682404756

Weld County, CO

NWSE Section 1 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: FHA #10-1
API: 05-123-12560



Photo 1. Photo taken from the eastern tank battery location, facing West. Operator has failed to perform final reclamation activities.

Inspection Photos
Location Name: FHA #10-1
API: 05-123-12560



Photo 2. Photo taken from the western tank battery location, facing South. Photo illustrates unmanaged weeds and weed debris at the location.

Inspection Photos
Location Name: FHA #10-1
API: 05-123-12560



Photo 3. Photo taken from the tank battery location, facing South towards the well location. Well location is in a fallow crop field. A follow up inspection will occur in the future to ensure compliance with Rule 1004 standards.