

Inspection Photos  
Location Name: Oxbow 0880 S29  
Location ID: 458790



**Photo 1. Silt fence compromised by snow removal.**



**Photo 2. Mud additives stored without covers.**