

# Inspection Photos

API: 05-071-07412

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 4/2/2019

## Inspection Photos



**Photo 1.** There is vehicle rutting along the main access road in the canyon.

## Inspection Photos



**Photo 2.** There is signs of erosion and vehicle rutting along the road that travels up to the location.

## Inspection Photos



**Photo 3.** There is some oil on the engine skid.