

**Inspection Photos**  
**Location Name: Ignacio 33-8 #2**  
**API: 05-067-05508**



**Excavation where Pit Facility ID #105402 had been located.**



**Remaining impacted material awaiting disposal.**



**Inspection Photos**  
**Location Name: Ignacio 33-8 #2**  
**API: 05-067-05508**



**Clean fill stockpiled on site.**



**Safety fencing installed during this inspection.**