

Inspection Photos
Location Name: UPV-65N66W /29NWNE
Location #: 336660



Photo #1

UPV 29-2H6 (05-123-18651) Wellsite
No Emergency contact number posted
from prior FIR



Photo #2

UPV 29-2H6 Wellsite
Emergency contact number NOW posted

Inspection Photos
Location Name: UPV-65N66W /29NWNE
Location #: 336660



Photo #3

Bensler J 29-17D (05-123-29137) Wellsite
No Emergency contact number posted
from prior FIR



Photo #4

Bensler J 29-17D Wellsite
Emergency contact number NOW posted

Inspection Photos
Location Name: UPV-65N66W /29NWNE
Location #: 336660



Photo #5

Bensler J 29-18D (05-123-29139) Wellsite
No Emergency contact number posted
from prior FIR



Photo #6

Bensler J 29-18D Wellsite
Emergency contact number NOW posted

Inspection Photos
Location Name: UPV-65N66W /29NWNE
Location #: 336660



Photo #7

Bensler J 29-21D (05-123-29136) Wellsite
No Emergency contact number posted
from prior FIR



Photo #8

Bensler J 29-21D Wellsite
Emergency contact number NOW posted

Inspection Photos
Location Name: UPV-65N66W /29NWNE
Location #: 336660



Photo #9

Bensler J 29-27D (05-123-29138) Wellsite
No Emergency contact number posted
from prior FIR



Photo #10

Bensler J 29-27D Wellsite
Emergency contact number NOW posted



Inspection Photos
Location Name: UPV-65N66W /29NWNE
Location #: 336660



Photo #11
UPV 29-1H6, 29-2H6
Bensler J 29-17D, 29-18D, 29-21D, 29-27D
Battery