

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/04/2019

Submitted Date:

04/04/2019

Document Number:

696300101

FIELD INSPECTION FORM

Loc ID 432817 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|--------------------------|---------|
| Kraich, Adam | | adam.kraich@state.co.us | |
| , | | cogccinspection@pdce.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 432815 | WELL | SI | 11/01/2018 | OW | 123-37296 | Anderson 34R-223 | SI |
| 432816 | WELL | SI | 11/01/2018 | OW | 123-37297 | Anderson 34R-343 | SI |
| 432818 | WELL | SI | 11/01/2018 | OW | 123-37298 | Anderson 34R-203 | SI |
| 432819 | WELL | SI | 11/01/2018 | OW | 123-37299 | Anderson 34R-403 | SI |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: Well 34R-203 is missing the wellhead sign

Corrective Action: Install sign to comply with Rule 210.b.

Date: 05/06/2019

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|-------------------|-------|--|
| Fencing/: | | | |
| Type | IGNITOR/COMBUSTOR | | |
| Comment: | Panel | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Panel | | |
| Corrective Action: | | Date: | |

| | | | |
|-------------------------------|-----------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Ancillary equipment | # 2 | | |
| Comment: | Automation RTUs | | |
| Corrective Action: | | Date: | |
| Type: Pig Station | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |

| | | | |
|-----------------------------------|-----|--|-------|
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: VRU | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heated Separator | # 4 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 4 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Compressor | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER | 2 | 100 BBLS | PBV FIBERGLASS | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|--|---------------------|---------------------|-------------|-----------------------|
| | | | | | |
| Comment: | Shares a berm with the Crude Oil tanks | | | | |
| Corrective Action: | | | | Date: | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 8 | 400 BBLS | STEEL AST | | 40.538120,-104.757280 |
| Comment: | | | | | |
| Corrective Action: | | | | | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
| | | | | |

| | | | | | |
|--------------------|----------|------------------|-----------------|----------|-------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected Facilities

Facility ID: 432815 Type: WELL API Number: 123-37296 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

Facility ID: 432816 Type: WELL API Number: 123-37297 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

Facility ID: 432818 Type: WELL API Number: 123-37298 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

Facility ID: 432819 Type: WELL API Number: 123-37299 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

COGCC Comments

| Comment | User | Date |
|---|--------|------------|
| On 04/04/2019, I Erica Petrie performed an inspection of the Anderson 34R-203 Wellhead and Tank Battery (Location ID 461666), owned and operated by PDC Energy INC. | petrie | 04/04/2019 |
| While on inspection I observed the following issue(s) Wellhead Anderson 34R-203 was missing the Wellhead sign, see photo #7, Cite rule 210.b END. | | |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 696300102 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4785285 |