

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/27/2019

Submitted Date:

03/29/2019

Document Number:

681701196**FIELD INSPECTION FORM**Loc ID 451421 Inspector Name: Arauza, Steven On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments
2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Wentzel, Dougo		dougo.wentzel@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Bankert, Wayne		wbankert@laramie-energy.com	
, Laramie		cogccnotifications@laramie-energy.com	All Inspections
Prescott, Lorne	(970) 812-5311	lprescott@laramie-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453889	SPILL OR RELEASE	AC	03/02/2018		-	Bruton 30-03	EI

General Comment:

COGCC Environmental Inspection of tank battery, conducted in response to verbal notification from the operator of a potential release inside of tank battery containment.

Tank battery consists of four (4) 400 bbl steel ASTs labeled to contain condensate/produced water, which are located inside of lined metal containment berm. On date of inspection, tank battery berm contained approximately 6-9 inches of fluids (water with hydrocarbon sheen and odor). See photos. No visible tears or holes were observed in visible portion of tank battery liner during inspection. No active source of the fluids observed inside of containment was determined by inspection.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume			

In Containment: Yes ☐Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spills/Releases:**Type of Spill: OTHER E&P WASTE

Estimated Spill Volume: _____

Comment: Presence of fluid inside of tank battery containment likely explained by accumulation of snowmelt. Fluids constitute oily waste, due to presence of hydrocarbon odor and sheen. See photos.

Corrective Action: Remove and properly dispose of oily waste, per Rule 907.e. Submit information regarding final disposition of fluids to the COGCC via a Field Inspection Report Response form. If fluids are determined to be the result of a spill or release from the production facility, submit an eForm 19 Spill Report per Rule 906.b.

Date: 04/12/2019

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Spill/Remediation:

Comment: Spill ID #453889 remains active for the subject facility. Supplemental eForm 19 received 2/21/2018 (doc #401549719) includes the following COGCC comment: "Benzene concentration is above Table 910-1 on sample 30-03-SS1 (0.29 mg/kg). The request for closure box was unchecked. Another round of samples is required to confirm compliance with Table 910-1. 3 samples, including one at the center of the spilled area is suggested." Remediation Project #11230 was approved to address impacts. Operator has not provided any project updates after Initial F27 (doc #401606653) was approved on 4/17/2018.

Corrective Action: Submit an update for Spill #453889 via an eForm 19 Supplemental Report. Operator may include a closure request indicating that work was proceeding under approved Remediation Project #11230. Submit an eForm 27 Supplemental Report to provide a project status update and additional documentation for Remediation Project #11230.

Date: 04/29/2019

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401990209	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4778502
681701199	20190327 Field Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4778501