

Inspection Photos
Operator: BP America
Location/API #: 067-08379
Date: 3-20-2019



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern project area facing eastward. Revegetation appears to be progressing within the interim reclamation areas.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of erosional rilling within the western project area.