

GORDON ENGINEERING INC

Api # 05-077-08408

Inspection # 675002124



Photo of location From NW corner of the location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

GORDON ENGINEERING INC

Api # 05-077-08408

Inspection # 675002124



Photo #2. Wellhead sign.



Photo # 3 Tank Battery (rust and in need of paint) 911 not posted.

GORDON ENGINEERING INC

Api # 05-077-08408

Inspection # 675002124



Photo #4. Holes in containment liner (north wall)



Photo # 5 Holes in containment liner (east corner)

GORDON ENGINEERING INC

Api # 05-077-08408

Inspection # 675002124



Photo #6 . Holes in containment liner (se corner)



Photo #7 Holes in containment liner (sw corner)

GORDON ENGINEERING INC

Api # 05-077-08408

Inspection # 675002124



Photo #8. Cable sticking out of the ground SE side of tank battery



Photo #9. Trash on location

GORDON ENGINEERING INC

Api # 05-077-08408

Inspection # 675002124



Photo #12. Unused equipment on south side of location



Photo #13. Unused riser that is not marked or locked out tagged out. Unused Gas meter and parts

GORDON ENGINEERING INC

Api # 05-077-08408

Inspection # 675002124



Photo #10. Unused riser in middle of location



Photo #11. hole in the ground in middle of location.

GORDON ENGINEERING INC

Api # 05-077-08408

Inspection # 675002124



Dangerous riser and hole in middle of location

GORDON ENGINEERING INC

Api # 05-077-08408

Inspection # 675002124



Erosion and sediment moving along entrance onto location.



**Erosion and sediment moving off NW corner of location
choking out vegetation.**