

Inspection Photos
Operator: BP America
Location/API #: 067-06950
Date: 3-20-2019



Photo 1. View of the project area from the southeastern edge facing center.



Photo 2. View of the eastern project area from the southwestern project area facing eastward. Revegetation appears to be progressing within the interim reclamation areas.



Photo 3. View of debris within the interim reclamation area.



Photo 5. View of debris within the interim reclamation area.