

Inspection Photos
Location Name: WEBER-66N66W /26NESE
Location #: 319160



Photo #1
Weber 1-26 (05-123-10805) Wellsite
Temporarily Abandoned | TA
Unused Equipment
from prior FIR



Photo #2
Weber 1-26 Wellsite
Temporarily Abandoned | TA
Unused Equipment - Removed

Inspection Photos
Location Name: WEBER-66N66W /26NE5E
Location #: 319160



Photo #3
Weber 1-26 Gas meter run
Unused Equipment - Automation controls
from prior FIR



Photo #4
Weber 1-26 Gas meter run
Unused Equipment - Automation controls
Removed



Inspection Photos

Location Name: WEBER-66N66W /26NESE

Location #: 319160



Colorado Oil & Gas Conservation Commission
40.45823, -104.73847, 1411.0m, 338°
2019/04/05 12:54:16 PM

Photo #5

Weber 1-26 Battery

Shut-down



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources