

**Inspection Photos**  
**Location Name: ROBERTS GOVERNMENT 1-4-3-2**  
**Location ID: 05-103-09765**  
**Inspection: 679703590**



**Photo 1. Location looking west.**



**Photo 2. Gas leaking into pit through pipe. Meter building ~500' from well location.**