

**Inspection Photos**  
**Location Name: FOSS-66N64W /13NENE**  
**Location #: 305307**



**Photo #1**

**Foss 13-11 (05-123-22778) Wellsite**  
**Plugged & Abandoned | PA**  
**NOT Cut & Capped – Temp. cap appears in place**  
**Incorrect Emergency contact number posted**  
*from prior FIR*



**Photo #2**

**Foss 13-11 Wellsite**  
**Plugged & Abandoned | PA**  
**≈ 75 yds.**  
**Reclamation Progressing**

**Inspection Photos**  
**Location Name:** FOSS-66N64W /13NENE  
**Location #:** 305307



**Photo #3**  
**Foss 13-11, 12, 13, 14, 15 Battery site**  
**Abandoned**  
**Reclamation in process**  
**Unused Equipment - Gas meter run**  
*from prior FIR*



**Photo #4**  
**Foss 13-11, 12, 13, 14, 15 Battery site**  
**Abandoned**  
**Reclamation progressing**  
**Unused Equipment - Gas meter run**  
**Removed**

