

Laramie Energy LLC
Api # 05-077-08724
Inspection # 675002130



Photo of location

Laramie Energy LLC
Api # 05-077-08724
Inspection # 675002130



Photo #2. Wellhead sign.

Photo # 3 Tank Battery

Laramie Energy LLC
Api # 05-077-08724
Inspection # 675002130



Photo #4 Tank need paint and has a lot of rust.

Laramie Energy LLC
Api # 05-077-08724
Inspection # 675002130



Photo #5 Erosion and sediment moving off location on the N side of location.

Photo #6 Erosion and sediment moving off location on W end of location into a BMP that needs maintained.

Laramie Energy LLC
Api # 05-077-08724
Inspection # 675002130



Photo # . Erosion and sediment moving off location into a ravine from a sediment filled ditch . (NW corner)

Photo #7 Erosion moving sediment off location on the NW end of location.

Laramie Energy LLC
Api # 05-077-08724
Inspection # 675002130



Sediment filled ditch. BMP needs maintenance on North end of location



Erosion moving sediment off location at entrance and along access road.