

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401999024

Date Received:

04/08/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Beebe, Sabre

970-779-9398

Sabre.Beebe@bpx.com

Labowskie, Steve

steve.labowskie@state.co.us

Inspections, All

SanJuanCOGCC@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 687904134

Inspection Date: 03/20/2019

FIR Submit Date: 03/20/2019

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 333870

Location Name: BARNES WTR DISP WELL Number: 4SWSE County: LA PLATA
(EPA)-N33N9W

Qtrqtr: SWSE Sec: 4 Twp: 33N Range: 9W Meridian: N

Latitude: 37.128716 Longitude: -107.829904

FACILITY - API Number: 05-067- -00 Facility ID: 264750

Facility Name: BARNES WTR DISP WELL Number: 1
(EPA)

Qtrqtr: SWSE Sec: 4 Twp: 33N Range: 9W Meridian: N

Latitude: 37.128716 Longitude: -107.829904

CORRECTIVE ACTIONS:

1 CA# 123380

Corrective Action: comply with Rule 605.d.

Date: 03/27/2019

Response: CA COMPLETED

Date of Completion: 03/27/2019

Attached you will find before and after photos of work on the BGT on this location. BPX dispatched personnel immediately upon reviewing the CA to close the thief hatch on the T-1427-1 tank."

Operator _____
Comment: _____

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Attached you will find before and after photos of work on the BGT on this location. BPX dispatched personnel immediately upon reviewing the CA to close the thief hatch on the T-1427-1 tank."

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 4/8/2019 9:10:31 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401999040	Closure document
-----------	------------------

Total Attach: 1 Files