

# Final Reclamation and Stormwater Inspection

March 28, 2019

Operator: GREAT WESTERN OPERATING COMPANY LLC # 10110

Location ID: 429796

Inspection Document #: 674902706

Weld County, CO

NENE Section 3 T3N R68W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: GREAT WESTERN OPERATING COMPANY /3N68W3

Location ID: 429796



**Photo 1.** Photo taken from the access road off CR 38, facing North. Appears the access road and gravel remain on location.



**Photo 2.** Photo taken from the access road looking into the location, facing South. See comments from Photo 1.

## Inspection Photos

Location Name: GREAT WESTERN OPERATING COMPANY /3N68W3

Location ID: 429796



**Photo 3.** Photo taken from the access road looking into the location, facing Southeast. Photo depicts the removal of all equipment has been performed. However final reclamation activities have not been performed at the time of inspection.



**Photo 4.** Photo taken from the location, facing South. See comments from Photo 3.

Inspection Photos

Location Name: GREAT WESTERN OPERATING COMPANY /3N68W3

Location ID: 429796



**Photo 5.** Photo taken from the location, facing North. See comments from Photo 3.



**Photo 6.** Photo taken from the location, facing Northeast. See comments from Photo 3.