

Inspection Photos
Operator: BP America
Location/API #: 067-07373
Date: 3-26-2019



Photo 1. View of the project area from the southeastern corner of the working area facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward.



Photo 3. View of the southern project area from the southeastern corner facing westward. What appears to be surface owner equipment is stored along the outer edge of the project area.