

# Final Reclamation and Stormwater Inspection

March 28, 2019

Operator: GREAT WESTERN OPERATING COMPANY LLC # 10110

Location ID: 424013

Inspection Document #: 674902707

Weld County, CO

SWNW Section 2 T3N R64W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: GREAT WESTERN OPERATING COMPANY /3N68W2

Location ID: 424013



**Photo 1.** Photo taken from the access road, facing East. Appears the gate and access road remain on location.



**Photo 2.** Photo taken from the access road, facing East. See comments from Photo 1.

## Inspection Photos

Location Name: GREAT WESTERN OPERATING COMPANY /3N68W2

Location ID: 424013



**Photo 3.** Photo taken from the location, facing Northeast. Photo depicts the removal of most equipment has been performed. However, equipment still remains on location. Gravel remains and location has not been re- contoured/re-graded.



**Photo 4.** Photo taken from along the access road, facing West. See comments from Photo 1.



## Inspection Photos

Location Name: GREAT WESTERN OPERATING COMPANY /3N68W2

Location ID: 424013



**Photo 5.** Photo taken from the location, facing West. See comments from Photo 3



**Photo 6.** Photo taken from the location, facing West. Photo depicts a hole on location approximately at least 3 feet deep.



## Inspection Photos

Location Name: GREAT WESTERN OPERATING COMPANY /3N68W2

Location ID: 424013



**Photo 7.** Photo taken from the location, facing Southeast. See comments from Photo 3.



**Photo 8.** Photo taken from the location, facing Southeast. Appears there is erosion on location.