

Final Reclamation and Stormwater Inspection

March 28, 2019

Operator: PDC ENERGY INC – 69175

Location ID: 319545

Inspection Document #: 674902710

Weld County, CO

SWSE Section 1 T3N R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: PDC ENERGY INC /3N68W1
Location ID: 319545



Photo 1. Photo taken from the location, facing Northeast. Appears the Operator has performed final reclamation activities, with the evidence of drilling rows .



Photo 2. Photo taken from the location, facing East. See comments from Photo 1.