

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/09/2019

Submitted Date:

04/09/2019

Document Number:

692601635

FIELD INSPECTION FORM
 Loc ID 337765 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288479	WELL	PR	07/01/2008	GW	125-10572	ROBERT & JOANN KLIE 23-27	PR

General Comment:

Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Trail through pasture		
Corrective Action:		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Arrow gas engine		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Sentry unit		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Gas scrubber		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:		
Type		

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	288479	Type:	WELL	API Number:	125-10572	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Central meter run for (R&J Klie 33-27, 22-27, 23-27, 24-27) 1300' E @ R&J Klie 33-27								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Location is grassed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT