

Inspection Photos
Location Name: New Elk #26-9
Location ID: 308666



Photo 1 loc pic



Photo 2 stained soil around WH

Inspection Photos
Location Name: New Elk #26-9
Location ID: 308666



Photo 3 Stained soil around fuel gas line to HYD skid



Photo 4 stained soil around HYD skid

Inspection Photos
Location Name: New Elk #26-9
Location ID: 308666



Colorado Oil and Gas Conservation Commission
37.14101, -104.95932, 2285.0m
Apr 9, 2019 14:07:06



Colorado Oil and Gas Conservation Commission
37.14105, -104.95925, 2285.4m
Apr 9, 2019 14:07:23

Photo 5 Trash outside separator house

Photo 6 Loc pic

Inspection Photos
Location Name: New Elk #26-9
Location ID: 308666



Colorado Oil and Gas Conservation Commission
37.14107, -104.95934, 2283.3m
Apr 9, 2019 14:07:45



Colorado Oil and Gas Conservation Commission
37.14107, -104.95935, 2285.0m
Apr 9, 2019 14:08:00

Photo 7 Stained soil around Liquid ring skid

Photo 8 stained soil around Liquid ring skid

Inspection Photos
Location Name: New Elk #26-9
Location ID: 308666



Photo 9 Stained soil around Liquid ring skid approximately 48in out from skid.

Photo 10 stained soil around Liquid ring skid approximately 48in out from skid.

Inspection Photos
Location Name: New Elk #26-9
Location ID: 308666



Photo 11 Stained soil around Liquid ring skid



Photo 10 stained soil around Liquid ring skis and unused equipment (batteries)