

**Inspection Photos**  
**Operator: BP America**  
**Location/API #: 067-09483**  
**Date: 3-26-2019**



Photo 1. View of the project area from the southwestern edge facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward.



Photo 3. View of erosional rilling within the southern project area.



Photo 4. View of the eastern project area from the southeastern corner facing northward.



Photo 5. View of erosional channel forming within the eastern project area.