

# Final Reclamation and Stormwater Inspection

March 28, 2019

Operator: KERR MCGEE OIL & GAS # 47120

Location ID: 329640

Inspection Document #: 674902714

Weld County, CO

NWNW Section 8 T3N R67W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: KERR MCGEE /3N67W8  
Location ID: 329640



**Photo 1.** Photo taken from the location, facing North. Appears Operator has performed final reclamation activities with the evidence of drill rows matching the adjacent cropland.



**Photo 2.** Photo taken from the location, facing Northeast. See comments from Photo 1.