

Final Reclamation and Stormwater Inspection

March 28, 2019

Operator: KERR MCGEE OIL & GAS # 47120

Location ID: 329641

Inspection Document #: 674902715

Weld County, CO

SWNW Section 8 T3N R67W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: KERR MCGEE /3N67W8
Location ID: 329641



Photo 1. Photo taken from the access road looking into the location, facing East. Appears Operator has performed final reclamation activities at the location with the evidence of drill rows matching the adjacent cropland.



Photo 2. Photo taken from the location, facing East. See comments from Photo 1.