

# Inspection Photos

4/09/2019

Operator: H & M PETROLEUM CORPORATION #  
10032

Location ID: 458288

Inspection Doc. Number: 682504721

Logan County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: H & M PETROLEUM CORPORATION # 10032  
Location ID: 458288



**Photo 1:** Photo taken from the east end of the location, facing south. Photo shows contractor on site was utilizing the soil stockpile salvaged from the pit, as material for the berms around the tank. Inspector discussed concerns regarding 1002.c with Mr. Dick Shanor who was also on location at time.



**Photo 2:** Photo taken from the southwest corner of the tank battery. Photo shows operator has updated the secondary containment.

Inspection Photos  
Operator: H & M PETROLEUM CORPORATION # 10032  
Location ID: 458288



**Photo 3:** Photo taken from the southwest corner of the tank battery. Photo shows operator has updated the secondary containment.



**Photo 4:** Photo taken from the red tank, facing east. Photo taken during a follow-up visit later in the day. Photo shows soils were returned to the stockpile and that the berms constructed and in proper functioning condition.



**Photo 5:** See comments under photo 4.