

Laramie Energy LLC Api

05-077-09349

Inspection # 675002138



Photo of location

Laramie Energy LLC Api
05-077-09349
Inspection # 675002138



Photo #2. Wellhead sign.



Photo # 3 Tank Battery

Laramie Energy LLC Api
05-077-09349
Inspection # 675002138



Hole in liner in containment



Multiple holes in liner

Laramie Energy LLC Api
05-077-09349
Inspection # 675002138



Stock pile of soil not protected on location with no containment



Soil pile with no containment not protected from erosion.