

Maralex Resources Inc.

Api # 05-077-08614

Inspection # 675002140



Photo of location

Maralex Resources Inc.
Api # 05-077-08614
Inspection # 675002140



Photo #2. Wellhead (no sign.) Debris



Photo # 3 Debris on location

Maralex Resources Inc.
Api # 05-077-08614
Inspection # 675002140



Stored tank on location



No tank label or faded tank label

Maralex Resources Inc.
Api # 05-077-08614
Inspection # 675002140



All equipment unhooked and set to the side on location.



. Tank unhooked and set to the side on location.

Maralex Resources Inc.
Api # 05-077-08614
Inspection # 675002140



Erosion and sediment moving on location



Erosion and sediment moving onto location from access road.