

Inspection Photos
Operator: BP America
Location/API #: 067-08835
Date: 3-26-2019



Photo 1. View of the project area from the northeastern corner of the project area facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Cement debris needs to be removed.



Photo 3. View of the eastern project area from the northeastern corner facing southward.