

Final Reclamation and Stormwater Inspection

March 29, 2019

Operator: EXTRACTION OIL & GAS INC – 10459

Location ID: 320337

Inspection Document #: 674902725

Broomfield County, CO

SESE Section 9 T1S R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: EXTRACTION OIL & GAS/1S68W9
Location ID: 320337



Photo 1. Photo taken from the access road off Lipan St., facing East. Appears the access road and gate remain on location.



Photo 2. Photo taken from the access road off Lipan St., facing West. See comments from Photo 1.

Inspection Photos
Location Name: EXTRACTION OIL & GAS/1S68W9
Location ID: 320337



Photo 3. Photo taken from the middle of the access road, facing East. See comments from Photo 1.



Photo 4. Photo taken from the access road, facing East. Appears Operator has performed final reclamation activities at the location with the evidence of drill rows. However, the reclamation is not at percent cover and has non-uniform establishment of perennial cover.

Inspection Photos
Location Name: EXTRACTION OIL & GAS/1S68W9
Location ID: 320337



Photo 5. Photo taken from the facility location, facing South. See comments from Photo 4.



Photo 6. Photo taken from the access road, facing West. See comments from Photo 1.