

**Inspection Photos**  
**Location Name: ME HEFLEY 8X**  
**Location ID: 05-103-03632**  
**Inspection: 679703632**



**Photo 1. Location looking west.**



**Photo 2. Broken deadman marker.**