

Inspection Photos
Location Name: GRAY A 19X
Location ID: 05-103-07873
Inspection: 679703648



Photo 1. Location looking southwest.



Photo 2. Deadman with broken marker.