

Inspection Photos
Operator: BP America
Location/API #: 067-09195
Date: 3-26-2019



Photo 1. View of the project area from the northeastern corner of the project area facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation appears to be progressing within the interim reclamation areas.



Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4. View of erosional channel forming within the northern project area.