

Inspection Photos
Location Name: Cabernet #42-4
Location ID: 309518



Photo 1 Gas meter run. Weeds in and around meter run



Photo 2 WH

Inspection Photos
Location Name: Cabernet #42-4
Location ID: 309518




Photo 3 Unused equipment, Stained soil, Unmarked, unused and not LOTO riser