

**Inspection Photos**  
**Location Name: MILNE-66N65W /18NENE**  
**Location #: 323272**



**Photo #1**  
**Milne #4 (05-123-12793) Wellsite**  
**Shut-In | SI**  
**Incorrect Emergency number posted**  
*from prior FIR*



**Photo #2**  
**Milne #4 Wellsite**  
**Shut-In | SI**  
**Correct Emergency number NOW posted**

**Inspection Photos**  
**Location Name: MILNE-66N65W /18NENE**  
**Location #: 323272**



**Photo #3**  
**Milne #4 Battery**  
**Produced H2O vault**  
**Capacity NOT posted**  
*from prior FIR*



**Photo #4**  
**Milne #4 Battery**  
**Produced H2O vault**  
**Capacity NOW posted**



**Inspection Photos**  
**Location Name:** MILNE-66N65W /18NENE  
**Location #:** 323272



Colorado Oil & Gas Conservation Commission  
40.49185, -104.69919, 1438.0m, 318°  
2019/03/12 04:58:54 PM

**Photo #5**  
**Milne #4 Battery**  
**Shut-down**  
*from prior FIR*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources